



Center for Family Services Headstart
35 E. Church Street
Blackwood, NJ 08021

1/5/2024 15:35
SAMPLE NUMBER: W8858
DATE SAMPLED: 12/27/23
DATE/TIME RECEIVED: 12/27/23 11:45
COLLECTED BY: Client

CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/l(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Time Sampled	DF	RL	Lead	Date/Time Analyzed
W8858-1	Kitchen Sink 1	12/27/23	8:00	1	0.002	<0.002	1/4/24 11:31
W8858-2	Kitchen Sink 2	12/27/23	8:05	1	0.002	0.00217	1/4/24 11:36
W8858-3	Kitchen Sink 3	12/27/23	8:08	1	0.002	0.00231	1/4/24 12:00
W8858-4	Water Cooler	12/27/23	8:10	1	0.002	<0.002	1/4/24 12:05
W8858-5	Utility Sink	12/27/23	8:15	1	0.002	<0.002	1/4/24 12:10
W8858-6	Mens Bathroom Sink	12/27/23	8:18	1	0.002	<0.002	1/4/24 12:15
W8858-7	Child Bathroom Sink 1	12/27/23	8:20	1	0.002	<0.002	1/4/24 12:20
W8858-8	Child Bathroom Sink 2	12/27/23	8:25	1	0.002	<0.002	1/4/24 12:25
W8858-9	Womens Bathroom Sink	12/27/23	8:30	1	0.002	<0.002	1/4/24 12:30

Latish Menghani
Lab Director



Center for Family Services Headstart
35 E. Church Street
Blackwood, NJ 08021

1/5/2024 15:43
SAMPLE NUMBER: W8858
DATE SAMPLED: 12/27/23
DATE/TIME RECEIVED: 12/27/23 11:45
COLLECTED BY: Client

CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/l(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Time Sampled	DF	RL	Copper	Date/Time Analyzed
W8858-1	Kitchen Sink 1	12/27/23	8:00	1	0.05	0.270	1/2/24 15:16
W8858-2	Kitchen Sink 2	12/27/23	8:05	1	0.05	0.429	1/2/24 15:16
W8858-3	Kitchen Sink 3	12/27/23	8:08	1	0.05	0.145	1/2/24 15:17
W8858-4	Water Cooler	12/27/23	8:10	1	0.05	<0.05	1/2/24 15:17
W8858-5	Utility Sink	12/27/23	8:15	1	0.05	0.223	1/2/24 15:18
W8858-6	Mens Bathroom Sink	12/27/23	8:18	1	0.05	0.214	1/2/24 15:19
W8858-7	Child Bathroom Sink 1	12/27/23	8:20	1	0.05	0.336	1/2/24 15:21
W8858-8	Child Bathroom Sink 2	12/27/23	8:25	1	0.05	0.269	1/2/24 15:23
W8858-9	Womens Bathroom Sink	12/27/23	8:30	1	0.05	0.274	1/2/24 15:23

Latish Menghani
Lab Director