



Center for Family Services Headstart
100 Maplegrove Boulevard
Lumberton, NJ 08048

7/20/2021 12:50
SAMPLE NUMBER: U5926
DATE SAMPLED: 6/30/21
DATE/TIME RECEIVED: 7/1/21 14:30
COLLECTED BY: Client

CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/l(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Sample Time	DF	RL	Copper	Date Analyzed
U5926-1	Classroom Sink #8 R	6/30/2021	8:05	1	0.05	0.110	7/8/21 12:50
U5926-2	Classroom Sink #8 L	6/30/2021	8:05	1	0.05	<0.05	7/8/21 12:50
U5926-3	Classroom Sink #3 R	6/30/2021	8:07	1	0.05	<0.05	7/8/21 12:52
U5926-4	Classroom Sink #3 L	6/30/2021	8:07	1	0.05	<0.05	7/8/21 12:52
U5926-5	Classroom Sink #4 L	6/30/2021	8:08	1	0.05	0.276	7/8/21 12:53
U5926-6	Classroom Sink #4 R	6/30/2021	8:08	1	0.05	0.262	7/8/21 12:53
U5926-7	Water Fountain 1	6/30/2021	8:12	1	0.05	0.219	7/8/21 12:54
U5926-8	Water Fountain 2	6/30/2021	8:12	1	0.05	0.250	7/8/21 12:54
U5926-9	Men's Staff R	6/30/2021	8:14	1	0.05	0.344	7/8/21 12:56
U5926-10	Men's Staff L	6/30/2021	8:14	1	0.05	0.237	7/8/21 12:57
U5926-11	Kitchen HW	6/30/2021	7:55	1	0.05	0.130	7/8/21 12:57
U5926-12	Kitchen Utility Sink #1	6/30/2021	7:57	1	0.05	0.194	7/8/21 12:58
U5926-13	Kitchen Utility Sink #2	6/30/2021	7:58	1	0.05	<0.05	7/8/21 12:59
U5926-14	Kitchen Utility Sink #3	6/30/2021	7:59	1	0.05	0.672	7/8/21 13:00
U5926-15	Classroom Sink #2 L	6/30/2021	8:00	1	0.05	0.243	7/8/21 13:00
U5926-16	Classroom Sink #2 R	6/30/2021	8:00	1	0.05	0.251	7/8/21 13:01
U5926-17	Classroom Sink #1 R	6/30/2021	8:02	1	0.05	0.423	7/8/21 13:07
U5926-18	Classroom Sink #1 L	6/30/2021	8:02	1	0.05	0.425	7/8/21 13:08
U5926-19	Classroom Sink #7 L	6/30/2021	8:04	1	0.05	0.386	7/8/21 13:08
U5926-20	Classroom Sink #7 R	6/30/2021	8:04	1	0.05	0.062	7/8/21 13:09
U5926-21	Women's Staff L	6/30/2021	8:15	1	0.05	0.269	7/8/21 13:09
U5926-22	Women's Staff R	6/30/2021	8:15	1	0.05	0.232	7/8/21 13:10
U5926-23	Water Fountain 3	6/30/2021	8:16	1	0.05	0.374	7/8/21 13:11
U5926-24	Water Fountain 4	6/30/2021	8:16	1	0.05	0.385	7/8/21 13:13
U5926-25	Classroom Sink #9 L	6/30/2021	8:18	1	0.05	0.288	7/8/21 13:14
U5926-26	Classroom Sink #9 R	6/30/2021	8:18	1	0.05	0.287	7/8/21 13:20
U5926-27	Classroom Sink #10 L	6/30/2021	8:20	1	0.05	0.265	7/8/21 13:21
U5926-28	Classroom Sink #10 R	6/30/2021	8:20	1	0.05	0.259	7/8/21 13:21
U5926-29	Classroom Sink # 5 R	6/30/2021	8:22	1	0.05	0.394	7/8/21 13:22
U5926-30	Classroom Sink #5 L	6/30/2021	8:22	1	0.05	0.282	7/8/21 13:22
U5926-31	Classroom Sink #6 R	6/30/2021	8:24	1	0.05	0.073	7/8/21 13:23
U5926-32	Classroom Sink #6 L	6/30/2021	8:24	1	0.05	0.083	7/8/21 13:23

Latish Menghani
Lab Director



Center for Family Services Headstart
100 Maplegrove Boulevard
Lumberton, NJ 08048

7/20/2021 12:50
SAMPLE NUMBER: U5926
DATE SAMPLED: 6/30/21
DATE/TIME RECEIVED: 7/1/21 14:30
COLLECTED BY: Client

CERTIFICATE OF ANALYSIS

N.J.D.E.P. CERTIFICATION # 06003

Results in mg/l(ppm) unless otherwise noted

Sample #	Sample Location	Date Sampled	Sample Time	DF	RL	Lead	Date Analyzed
U5926-1	Classroom Sink #8 R	6/30/2021	8:05	1	0.002	0.0198	7/13/21 11:19
U5926-2	Classroom Sink #8 L	6/30/2021	8:05	1	0.002	<0.002	7/13/21 11:24
U5926-3	Classroom Sink #3 R	6/30/2021	8:07	1	0.002	<0.002	7/13/21 11:29
U5926-4	Classroom Sink #3 L	6/30/2021	8:07	1	0.002	<0.002	7/13/21 11:34
U5926-5	Classroom Sink #4 L	6/30/2021	8:08	1	0.002	<0.002	7/13/21 11:39
U5926-6	Classroom Sink #4 R	6/30/2021	8:08	1	0.002	<0.002	7/13/21 11:45
U5926-7	Water Fountain 1	6/30/2021	8:12	1	0.002	<0.002	7/13/21 12:00
U5926-8	Water Fountain 2	6/30/2021	8:12	1	0.002	<0.002	7/8/21 10:57
U5926-9	Men's Staff R	6/30/2021	8:14	1	0.002	0.0027	7/8/21 11:02
U5926-10	Men's Staff L	6/30/2021	8:14	1	0.002	0.0024	7/8/21 11:07
U5926-11	Kitchen HW	6/30/2021	7:55	1	0.002	<0.002	7/8/21 12:19
U5926-12	Kitchen Utility Sink #1	6/30/2021	7:57	1	0.002	<0.002	7/8/21 12:24
U5926-13	Kitchen Utility Sink #2	6/30/2021	7:58	1	0.002	<0.002	7/8/21 12:29
U5926-14	Kitchen Utility Sink #3	6/30/2021	7:59	1	0.002	0.0031	7/8/21 12:34
U5926-15	Classroom Sink #2 L	6/30/2021	8:00	1	0.002	<0.002	7/8/21 13:59
U5926-16	Classroom Sink #2 R	6/30/2021	8:00	1	0.002	<0.002	7/8/21 14:14
U5926-17	Classroom Sink #1 R	6/30/2021	8:02	1	0.002	<0.002	7/8/21 14:20
U5926-18	Classroom Sink #1 L	6/30/2021	8:02	1	0.002	<0.002	7/8/21 14:25
U5926-19	Classroom Sink #7 L	6/30/2021	8:04	1	0.002	<0.002	7/8/21 14:30
U5926-20	Classroom Sink #7 R	6/30/2021	8:04	1	0.002	0.0029	7/8/21 14:35
U5926-21	Women's Staff L	6/30/2021	8:15	1	0.002	<0.002	7/8/21 14:40
U5926-22	Women's Staff R	6/30/2021	8:15	1	0.002	<0.002	7/8/21 14:56
U5926-23	Water Fountain 3	6/30/2021	8:16	1	0.002	<0.002	7/8/21 15:01
U5926-24	Water Fountain 4	6/30/2021	8:16	1	0.002	<0.002	7/8/21 15:06
U5926-25	Classroom Sink #9 L	6/30/2021	8:18	1	0.002	<0.002	7/8/21 15:11
U5926-26	Classroom Sink #9 R	6/30/2021	8:18	1	0.002	<0.002	7/8/21 15:26
U5926-27	Classroom Sink #10 L	6/30/2021	8:20	1	0.002	<0.002	7/8/21 15:31
U5926-28	Classroom Sink #10 R	6/30/2021	8:20	1	0.002	<0.002	7/8/21 15:36
U5926-29	Classroom Sink # 5 R	6/30/2021	8:22	1	0.002	<0.002	7/8/21 15:51
U5926-30	Classroom Sink #5 L	6/30/2021	8:22	1	0.002	<0.002	7/8/21 15:57
U5926-31	Classroom Sink #6 R	6/30/2021	8:24	1	0.002	<0.002	7/8/21 16:02
U5926-32	Classroom Sink #6 L	6/30/2021	8:24	1	0.002	<0.002	7/8/21 16:07

Latish Menghani
Lab Director

Attachment C – Drinking Water Outlet Inventory

(Complete for each school)

Name of School: CFS Head Start at Lumberton Address: 100 Maple Grove Blvd, Lumberton NJ

Grade Levels: Pre-K Year School Constructed:

Individual school project officer Name/Signature: Joseph Flood Date Completed: 6-30-21

#1	Type	Location	Code	Operational ² (Y/N)	Signs of Corrosion ³ (Y/N)	Filter ⁴ (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	Kitchen HW	U5926-11	Y	N	N	Y	Y	N	N			
2	Sink	Kitchen Utility Sink #1	U5926-12	Y	N	N	Y	Y	N	N			
3	Sink	Kitchen Utility Sink #2	U5926-13	Y	N	N	Y	Y	N	N			
4	Sink	Kitchen Utility Sink #3	U5926-14	Y	N	N	Y	Y	N	N			
5	Sink	Classroom Sink #2 L	U5926-15	Y	N	N	Y	Y	N	N			

¹ Number outlets starting at the closest outlet to the Point of Entry (POE).

² Document if permanently or temporarily out of service on the Attachment B- Plumbing Profile.

³ Signs of corrosion detected, such as but not limited to frequent leaks, rust-colored water, or stained fixtures, dishes, or laundry.

⁴ Document on Attachment D- Filter Inventory.

6	Sink	Classroom Sink #2 R	U5926-16	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
7	Sink	Classroom Sink #1 R	U5926-17	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
8	Sink	Classroom Sink #1 L	U5926-18	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
9	Sink	Classroom Sink #7 L	U5926-19	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
10	Sink	Classroom Sink #7 R	U5926-20	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
11	Sink	Classroom Sink #8 R	U5926-1	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
12	Sink	Classroom Sink #8 L	U5926-2	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
13	Sink	Classroom Sink #3 R	U5926-3	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
14	Sink	Classroom Sink #3 L	U5926-4	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
15	Sink	Classroom Sink #4 L	U5926-5	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
16	Sink	Classroom Sink #4 R	U5926-6	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
17	Sink	Water Fountain 1	U5926-7	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
18	Sink	Water Fountain 2	U5926-8	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
19	Sink	Men's Staff R	U5926-9	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
20	Sink	Men's Staff L	U5926-10	Y	N	N	N	N	N	Y	Y	Y	N	N	N			
21	Sink	Women's Staff L	U5926-21	Y	N	N	N	N	N	Y	Y	Y	N	N	N			

22	Sink	Women's Staff R	U5926-22	Y		N	N	N	Y	Y	N	N	N				
23	Sink	Water Fountain 3	U5926-23	Y		N	N	N	Y	Y	N	N	N				
24	Sink	Water Fountain 4	U5926-24	Y		N	N	N	Y	Y	N	N	N				
25	Sink	Classroom Sink #9 L	U5926-25	Y		N	N	N	Y	Y	N	N	N				
26	Sink	Classroom Sink #9 R	U5926-26	Y		N	N	N	Y	Y	N	N	N				
27	Sink	Classroom Sink #10 L	U5926-27	Y		N	N	N	Y	Y	N	N	N				
28	Sink	Classroom Sink #10 R	U5926-28	Y		N	N	N	Y	Y	N	N	N				
29	Sink	Classroom Sink #5 R	U5926-29	Y		N	N	N	Y	Y	N	N	N				
30	Sink	Classroom Sink #5 L	U5926-30	Y		N	N	N	Y	Y	N	N	N				
31	Sink	Classroom Sink #6 R	U5926-31	Y		N	N	N	Y	Y	N	N	N				
32	Sink	Classroom Sink #6 L	U5926-32	Y		N	N	N	Y	Y	N	N	N				

Attachment C – Drinking Water Outlet Inventory

(Complete for each school)

Name of School: CFS Head Start at Lumberton Address: 100 Maple Grove Blvd, Lumberton NJ

Grade Levels: Pre-K Year School Constructed:

Individual school project officer Name/Signature: Joseph Flood Date Completed: 6-30-21

#1	Type	Location	Code	Operational ² (Y/N)	Signs of Corrosion ³ (Y/N)	Filter ⁴ (Y/N)	Brass Fittings, Faucets or valves? (Y/N)	Aerator/ Screen (Y/N)	Motion Activated (Y/N)	Chiller (Y/N)	Water Cooler		Comments
											Make	Model	
1	Sink	Kitchen HW	U5926-11	Y	N	N	Y	Y	N	N			
2	Sink	Kitchen Utility Sink #1	U5926-12	Y	N	N	Y	Y	N	N			
3	Sink	Kitchen Utility Sink #2	U5926-13	Y	N	N	Y	Y	N	N			
4	Sink	Kitchen Utility Sink #3	U5926-14	Y	N	N	Y	Y	N	N			
5	Sink	Classroom Sink #2 L	U5926-15	Y	N	N	Y	Y	N	N			

¹ Number outlets starting at the closest outlet to the Point of Entry (POE).

² Document if permanently or temporarily out of service on the Attachment B- Plumbing Profile.

³ Signs of corrosion detected, such as but not limited to frequent leaks, rust-colored water, or stained fixtures, dishes, or laundry.

⁴ Document on Attachment D- Filter Inventory.

6	Sink	Classroom Sink #2 R	U5926-16	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
7	Sink	Classroom Sink #1 R	U5926-17	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
8	Sink	Classroom Sink #1 L	U5926-18	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
9	Sink	Classroom Sink #7 L	U5926-19	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
10	Sink	Classroom Sink #7 R	U5926-20	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
11	Sink	Classroom Sink #8 R	U5926-1	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
12	Sink	Classroom Sink #8 L	U5926-2	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
13	Sink	Classroom Sink #3 R	U5926-3	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
14	Sink	Classroom Sink #3 L	U5926-4	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
15	Sink	Classroom Sink #4 L	U5926-5	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
16	Sink	Classroom Sink #4 R	U5926-6	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
17	Sink	Water Fountain 1	U5926-7	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
18	Sink	Water Fountain 2	U5926-8	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
19	Sink	Men's Staff R	U5926-9	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
20	Sink	Men's Staff L	U5926-10	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N
21	Sink	Women's Staff L	U5926-21	Y	N	N	N	N	Y	Y	N	N	N	N	N	N	N

22	Sink	Women's Staff R	U5926-22	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
23	Sink	Water Fountain 3	U5926-23	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
24	Sink	Water Fountain 4	U5926-24	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
25	Sink	Classroom Sink #9 L	U5926-25	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
26	Sink	Classroom Sink #9 R	U5926-26	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
27	Sink	Classroom Sink #10 L	U5926-27	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
28	Sink	Classroom Sink #10 R	U5926-28	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
29	Sink	Classroom Sink #5 R	U5926-29	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
30	Sink	Classroom Sink #5 L	U5926-30	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
31	Sink	Classroom Sink #6 R	U5926-31	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N
32	Sink	Classroom Sink #6 L	U5926-32	Y		N	N	N	N	N	N	N	N	N	N	N	N	N	N